

Assessment Requirements

Unit PO03C – Demonstrating Competency in Working with Plastic Materials and Components

General Requirements

You must:

1. produce evidence to show you meet **all** of the Learning Outcomes
2. produce performance evidence resulting from work you have carried out on real vehicles in your normal workplace or as defined within the IMI VCQ Assessment Strategy as managed and organised by an approved centre when naturally occurring performance evidence does not occur at frequent intervals in your normal workplace or when safety is at risk.
3. be observed by an assessor as defined in the IMI VCQ Assessment Strategy.
4. produce evidence from your normal workplace of carrying out **each** of the following listed below on at **least 2 occasions** (only use the flexible additive on **one occasion**).
 - Apply foundation coats including adhesion promoters
 - Applying top coats
 - use flexible additive
5. be observed by your assessor on **at least 1 occasion**, applying foundation and topcoat materials.